State of Washington Division of Industrial Safety and Health

INDUSTRIAL HYGIENE INSPECTION SUMMARY FOR: Roberts Environmental Services Inc. 1719 Irving Rd. Eugene, Oregon 97402 & ASARCO Plant, Tacoma

Inspection # 375230 ID # L6601 Inspector: D. Lofgren Report Date: 3-2-87

AR 10.3

An inspection was initiated on 1-22-87 for Roberts Environmental at ASARCO due to both an OHR and a complaint. The company was found to be an asbestos abatement contractor removing asbestos from structures prior to their demolition. The plant is in the process of being demolished and is under EPA supervision as a hazardous waste site.

An initial evaluation found that certified workers were being used and regulations regarding asbestos control were being followed. The company had been at the site less than a week at the time of the opening conference and was advised of the WISHA standard for arsenic and their need for complying. Asbestos removal was being conducted in areas of relatively low arsenic contamination. Other priority inspections at the site were conducted.

Monitoring for arsenic and asbestos was conducted on 2-19-87 after it was learned via a complaint that the company was working inside structures with high potential for excessive arsenic and asbestos exposure. Additional work in contaminated structures was planned. Sample analysis was requested on a rush basis. The Data Summary shows that high levels of arsenic were found. The aspestos removal was done in the plate treater #1 where the insides of the structure were contaminated with flue dust containing high percentages of arsenic trioxide and lead. One sample for asbestos was too overloaded for counting. The high total particulate level was indicative of insufficient use of water as a dust suppressant. It was learned that Inadequate head covering had been used for the job for several days until this inspector visited the site due to the complaint and pointed out the probable violation due to skin contact with arsenic and potential for skin damage. The employer responded the same day with improvements in respirator and body covering, but the immediate project was at an end. This inspector had previously discussed with the superintendent the need for better covering and respirators should they ever have to work inside contaminated structures.

Other allegations about dry removal of asbestos could not be documented. The completion of one job resulted in minor amounts of asbestos residue outdoors. The employer was cautioned to better police the areas upon completion of a job.

The inspection was closed on 3-2-87. The following general violations were issued: not maintaining safety meeting minutes at the site; not taking asbestos samples representative of the eight hour time weighted average; no written arsenic control program; incomplete written operating procedures for use of respirators as protection from asbestos and arsenic and; no arsenic hazard training for some employees. Serious violations were issued for failure to use adequate amounts of water to suppress arsenic dust, and failure to use adequate head covering for high exposure to arsenic and provide protective boots at no cost to the employees.

USEPA SF 1360145 State of Washington Division of Industrial Safety and Health For: Roberts Environmental

#375230

Sample Date: 2-17-87

Data Summary - Asbestos Demo. in Plate Treater #1, ASARCO

Name	Operation	Sample time, min.	Sampled Expos Total particulate mg/m ³	ure Inorgani arsenic Ag/m ³	c lead µg/m3	asbestos fibers/cc	8-hour T Inorgani arsenic µg/m ³		asbestos fibers/cc
Percy Nicholas	asbestos re- moval, con- taminent area wash down	210 102	13.2 1.1	1100 59	266 13	-	494	119	· •
Lonnie Miller	asbestos re- moval, con- taminent area wash down	205 40 60				** 0.05 0.04		-	**
Walter O'Mealy	asbestos re- moval, double bag section	212 98	1.8 0.16	259 <54	46 <5	- -	114	20	-

Note: The WISHA 8-hour TWA limits for the above contaminants are as follows: arsenic - $10 \,\mu\text{g/m}^3$; lead - $50 \,\mu\text{g/m}^3$ (150 $\,\mu\text{g/m}^3$ for construction); asbestos - 0.2 fibers/cc, proposed.

^{*} Eight hour time weighted average

^{**} Sample fiber overload with dust and asbestos fibers, unable to count